Table 4-	B: Injection Wells: Violations and CamWest I	Lander Oil Field nWest, Inc.		
Well Name	Type of Violation	Date Violation Began	Date Violation Ended	CamWest Return to Compliance
	Injection Over Pressure	9/1/97	9/30/97	Corrected pressure
	Injection Over Pressure	10/1/97	10/31/97	Corrected pressure
	Injection Over Pressure	1/1/98	1/31/98	Corrected pressure
# 9	Injection Over Pressure	7/1/98	8/31/98	Corrected pressure
# 9	Injection Over Pressure	3/1/99	12/31/99	Corrected pressure
	Injection Over Pressure	1/1/01	2/28/01	Corrected pressure
	Injection Over Pressure	6/1/01	9/30/01	Corrected pressure
	Late 5-yr MIT ¹	8/4/97	3/11/98	Pass MIT 3/11/98
# 12	Fail to demonstrate non-endangerment or plug and abandon	7/1/97	10/27/00	Pass MIT 10/27/00
·	Late 5-yr MIT	8/3/97	3/20/98	New violation occurs ²
# 13	Fail to establish and maintain MI ³	6/20/98	7/13/02	Repair, inject Phosphoria Pass MIT 7/13/02
. # 13	Injection Over Pressure	9/1/97	10/31/97	Corrected pressure
	Failure to report properly - Scab-lined well without depth-to-fluid measured	5/22/03	7/10/03	Made necessary fluid depth measurement
#15	Late 5-yr MIT	8/27/97	3/20/98	Pass MIT 3/20/98
# 15	Operation and Maintenance	7/8/03	8/18/03	Repositioned wellhouse to allow inspection

Table 4-B:	Injection Wells: Violations a	and Compliance st Limited Part		Lander Oil Field West, Inc.
Well Name	Type of Violation	Date Violation Began	Date Violation Ended	CamWest Return to Compliance
	Injection Over Pressure	9/1/97	10/31/97	Corrected pressure
	Injection Over Pressure	1/1/98	2/28/98	Corrected pressure
	Injection Over Pressure	4/1/98	6/30/98	Corrected pressure
	Injection Over Pressure	10/01/98	10/31/98	Corrected pressure
# 19	Injection Over Pressure	6/1/99	12/31/99	Corrected pressure
	Injection Over Pressure	1/1/01	1/31/01	Corrected pressure
	Injection Over Pressure	3/1/01	3/31/01	Corrected pressure
	Injection Over Pressure	9/1/01	9/30/01	Corrected pressure
	Late 5-yr MIT	9/2/99	9/7/01	Pass MIT 9/7/01
	Injection Over Pressure	9/1/97	10/31/97	Corrected pressure
	Injection Over Pressure	1/1/98	2/28/98	Corrected pressure
#27	Injection Over Pressure	7/1/98	8/30/98	Corrected pressure
#27	Injection Over Pressure	4/1/99	12/31/99	Corrected pressure
	Injection Over Pressure	1/1/01	4/30/01	Corrected pressure
	Injection Over Pressure	6/1/01	6/30/01	Corrected pressure

Fable 4-B: Injection Wells: Violations and Compliance CamWest Limited Partnership; CamWest, Inc. Lander						
Well Name	Type of Violation	Date Violation Began	Date Violation Ended	CamWest Return to Compliance		
	Injection Over Pressure	8/1/01	9/30/01	Corrected pressure		
	Late 5-yr MIT	10/5/99	9/17/01	Pass MIT 9/17/01		
	Injection Over Pressure	7/8/03	7/8/03	Only observed during inspection		
	Injection Over Pressure	9/1/97	10/31/97	Corrected pressure		
# 20	Injection Over Pressure	12/1/97	12/31/97	Corrected pressure		
# 29	Injection Over Pressure	4/1/98	6/30/98	Corrected pressure		
	Injection Over Pressure	7/1/99	7/31/99	Corrected pressure		
# 33	Late 1-yr MIT	7/1/97	11/07/01	Pass MIT 11/7/01		
	Fail to establish and maintain MI	7/1/97	10/25/97	New violation occurs		
# 34	Fail to demonstrate non-endangerment or plug and abandon	10/26/97	7/17/02	Repair, inject Phosphoria Pass MIT 7/17/02		
	Failure to report properly - Scab-lined well without depth-to-fluid measured	5/22/03	7/10/03	Made necessary fluid depth measurement		
# 44	Late 5-yr MIT	7/1/97	9/11/01	Pass MIT 9/11/01		
# 44	Failure to Report Fluid Analysis	2/15/04	5/12/04	Reported required fluid analysis		
	Late 1-yr MIT	11/1/97	11/6/01	Repair, inject Phosphoria Pass MIT 11/6/01		
# 45	Failure to report properly - Scab-lined well without depth-to-fluid measured	5/22/03	7/10/03	Made necessary fluid depth measurement		

Table 4-	B: Injection Wells: Violations an CamWest	Lander Oil Field West, Inc.		
Well Name	Type of Violation	Date Violation Began	Date Violation Ended	CamWest Return to Compliance
<i></i>	Late 5-yr MIT - then passed	8/3/97	3/19/98	Pass MIT 3/19/98
# 51	Injection Over Pressure	6/1/03	6/30/03	Corrected pressure
# 53	Injection Over Pressure	4/1/98	4/30/98	Corrected pressure
# 33	Late 5-yr MIT	7/1/97	9/25/01	Pass MIT 9/25/01
	Injection Over Pressure	9/1/97	10/31/97	Corrected pressure
	Injection Over Pressure	11/1/97	11/30/97	Corrected pressure
# 62	Injection Over Pressure	6/1/99	6/30/99	Corrected pressure
# 02 -	Injection Over Pressure	8/1/99	9/30/99	Corrected pressure
	Injection Over Pressure	11/1/99	11/30/99	Corrected pressure
	Late 5-yr MIT - then passed	7/1/97	3/12/98	Pass MIT 3/12/98
# 70	Late 1-yr MIT	3/21/98	9/6/01	Pass MIT 9/6/01
# 78	Late 5-yr MIT	7/1/97	9/11/01	Pass MIT 9/11/01
# /0	Failure to Report Fluid Analysis	2/15/04	5/12/04	Reported required fluid analysis
# 79	Injection Over Pressure	12/1/97	12/31/97	Corrected pressure
# /9	Injection Over Pressure	1/1/98	3/31/98	Corrected pressure

CamWest Limited Partnership; CamWest, Inc.							
Well Name	Type of Violation	Date Violation Began	Date Violation Ended	CamWest Return to Compliance			
	Injection Over Pressure	5/1/98	6/30/98	Corrected pressure			
	Injection Over Pressure	1/1/99	1/31/99	Corrected pressure			
	Injection Over Pressure	8/1/99	9/30/99	Corrected pressure			
	Injection Over Pressure	1/1/01	3/31/01	Corrected pressure			
	Injection Over Pressure	8/1/01	9/30/01	Corrected pressure			
	Late 1-yr MIT	12/23/97	9/5/01	Pass MIT 9/5/01			
	Injection Over Pressure	7/8/03	7/8/03	Only observed during inspection			
	Injection Over Pressure	9/1/97	9/30/97	Corrected pressure			
	Injection Over Pressure	1/1/98	2/28/98	Corrected pressure			
# 80	Injection Over Pressure	5/1/98	6/30/98	Corrected pressure			
# 60	Injection Over Pressure	5/1/99	12/31/99	Corrected pressure			
	Injection Over Pressure	9/1/01	9/30/01	Corrected pressure			
	Late 5-yr MIT - then passed	8/4/97	3/19/98	Pass MIT 3/19/98			
# 85	Fail to demonstrate non-endangerment or plug and abandon	7/1/97	7/16/02	PA'd ⁴ 7/16/02			
# 88	Late 5-yr MIT	8/4/97	3/17/98	New violation occurs failed MIT on 3/17/98, but continued inject			

Γable 4-	able 4-B: Injection Wells: Violations and Compliance CamWest Limited Partnership; CamWest, Inc. Lander Oil						
Well Name	Type of Violation	Date Violation Began	Date Violation Ended	CamWest Return to Compliance			
	Unauthorized Injection	3/17/98	4/30/98	Ceased injection by 4/30/98			
	Fail to maintain MI	6/17/98	9/13/01	Pass MIT			
	Fail to establish and maintain MI	1/6/03	1/14/03	Repair well, pass MIT 1/14/03			
	Failure to report properly - Scab-lined well without depth-to-fluid measured	5/22/03	7/10/03	Made necessary fluid depth measurement			
	Injection Over Pressure (L)	9/1/97	12/31/97	Corrected pressure			
	Injection Over Pressure (U)	9/1/97	10/31/97	Corrected pressure			
	Injection Over Pressure (U)	12/1/97	12/31/97	Corrected pressure			
	Injection Over Pressure (L)	1/1/98	3/30/98	Corrected pressure			
# 91	Injection Over Pressure (L)	7/1/98	12/31/98	Corrected pressure			
	Injection Over Pressure (U)	1/1/99	12/31/99	Corrected pressure			
	Injection Over Pressure (L)	1/1/01	9/30/01	Corrected pressure			
	Injection Over Pressure (U)	1/1/01	2/28/01	Corrected pressure			
	Late 5-yr MIT	10/6/99	9/17/01	Pass MIT 9/17/01			
400	Injection Over Pressure	10/1/97	11/30/97	Corrected pressure			
# 98	Injection Over Pressure	1/1/98	1/31/98	Corrected pressure			

Consent Decree: United States v. BP America Production Company fka Amoco Production Company, 7 CamWest, Inc. and CamWest Limited Partnership

able 4-	B: Injection Wells: Violations and CamWest I	Lander Oil Fiel West, Inc.		
Well Name	Type of Violation	Date Violation Began	Date Violation Ended	CamWest Return to Compliance
	Injection Over Pressure	7/1/99	12/31/99	Corrected pressure
	Injection Over Pressure	1/1/01	1/31/01	Corrected pressure
	Late 5-yr MIT	6/28/98	9/14/01	Pass MIT 9/14/01
# 107	Fail to demonstrate non-endangerment or plug and abandon	7/1/97	6/22/02	PA'd 6/22/02
	Injection Over Pressure	9/1/97	12/31/97	Corrected pressure
	Injection Over Pressure	1/1/98	10/31/98	Corrected pressure
	Injection Over Pressure	2/1/99	12/31/99	Corrected pressure
# 100	Injection Over Pressure	1/1/01	1/31/01	Corrected pressure
# 109	Injection Over Pressure	4/1/01	7/31/01	Corrected pressure
	Injection Over Pressure	9/1/01	9/30/01	Corrected pressure
	Late 5-yr MIT	8/4/97	3/17/98	Pass MIT 3/17/98
	Injection Over Pressure	5/1/03	5/30/03	Corrected pressure
# 113	Injection Over Pressure (U)	9/1/97	10/31/97	Corrected pressure
# 113	Injection Over Pressure (L)	5/1/98	5/31/98	Corrected pressure

Table 4-	Γable 4-B: Injection Wells: Violations and Compliance CamWest Limited Partnership; CamWest, Inc. Lander Oil F							
Well Name	Type of Violation	Date Violation Began	Date Violation Ended	CamWest Return to Compliance				
	Injection Over Pressure (L)	11/1/98	11/30/98	Corrected pressure				
	Injection Over Pressure (U)	4/1/98	6/30/98	Corrected pressure				
	Injection Over Pressure (U)	7/1/99	12/31/99	Corrected pressure				
	Injection Over Pressure (L)	7/1/99	12/31/99	Corrected pressure				
	Injection Over Pressure (U)	1/1/01	1/31/01	Corrected pressure				
	Injection Over Pressure (U)	3/1/01	9/30/01	Corrected pressure				
-	Late 1-yr MIT	10/27/98	7/9/02	Pass MIT 7/9/02 after reconfiguring well to allow MI demonstration				
	Injection Over Pressure (U)	4/1/01	5/31/01	Corrected pressure				
	Injection Over Pressure (U)	8/1/01	8/30/01	Corrected pressure				
# 115	Fail to estab. and maintain MI	3/5/98	7/24/98	Corrected pressure				
	Late 1-yr MIT	10/16/01	7/25/02	Pass MIT 7/25/02 after reconfiguring well to allow MI demonstration				
	Injection Over Pressure (L)	7/8/03	7/8/03	Only observed during inspection				
	Injection Over Pressure	1/1/98	1/31/98	Corrected pressure				
# 123	Injection Over Pressure	7/1/99	7/31/99	Corrected pressure				
	Injection Over Pressure	9/1/99	9/30/99	Corrected pressure				

Cable 4-B: Injection Wells: Violations and Compliance Lander Oil F CamWest Limited Partnership; CamWest, Inc.							
Well Name	Type of Violation	Date Violation Began	Date Violation Ended	CamWest Return to Compliance			
	Late 5-yr MIT	6/28/98	9/7/01	Pass MIT 9/7/01			
# 128	Late 5-yr MIT	9/12/99	9/12/01	Pass MIT 9/12/01			
	Injection Over Pressure	9/1/97	12/31/97	Corrected pressure			
	Injection Over Pressure	1/1/98	6/30/98	Corrected pressure			
	Injection Over Pressure	2/1/99	2/28/99	Corrected pressure			
	Injection Over Pressure	5/1/99	12/31/99	Corrected pressure			
	Injection Over Pressure	1/1/01	1/31/01	Corrected pressure			
# 129	Injection Over Pressure	3/1/01	3/31/01	Corrected pressure			
	Injection Over Pressure	6/1/01	9/30/01	Corrected pressure			
	Late 5-yr MIT - then passed	8/4/97	3/19/98	Pass MIT 3/19/98			
	Injection Over Pressure	7/8/03	7/8/03	Only observed during inspection			
	Injection Over Pressure	2/1/03	2/28/03	Corrected pressure			
" 122	Injection Over Pressure	4/1/98	4/30/98	Corrected pressure			
# 132	Failure to Report Fluid Analysis	2/15/04	5/12/04	Reported required fluid analysis			
# 134	Injection Over Pressure	4/1/98	4/30/98	Corrected pressure			

Consent Decree: <u>United States v. BP America Production Company fka Amoco Production Company</u>, 10 <u>CamWest, Inc. and CamWest Limited Partnership</u>

Table 4-B	: Injection Wells: Violations ar CamWes	Lander Oil Field nWest, Inc.		
Well Name	Type of Violation	Date Violation Began	Date Violation Ended	CamWest Return to Compliance
	Late 5-yr MIT	7/1/97	10/10/01	Pass MIT 10/10/01
	Injection Over Pressure (L)	9/1/97	12/31/97	Corrected pressure
	Injection Over Pressure (U)	7/1/97	12/31/97	Corrected pressure
	Injection Over Pressure (L)	1/1/98	1/31/98	Corrected pressure
	Injection Over Pressure (L)	9/1/98	9/30/98	Corrected pressure
	Injection Over Pressure (U)	1/1/98	1/31/98	Corrected pressure
# 150	Injection Over Pressure (U)	3/1/98	3/31/98	Corrected pressure
#130	Injection Over Pressure (U)	9/1/98	9/30/98	Corrected pressure
	Injection Over Pressure (L)	4/1/99	9/30/99	Corrected pressure
	Injection Over Pressure (L)	11/1/99	11/30/99	Corrected pressure
	Injection Over Pressure (U)	1/1/01	4/30/01	Corrected pressure
	Late 5-yr MIT	8/5/97	10/10/00	Pass MIT 10/10/00
	Late 1-yr MIT	10/11/01	7/25/02	Pass MIT 7/25/02 after reconfiguring well to allow MI demonstration

Consent Decree: <u>United States v. BP America Production Company fka Amoco Production Company</u>, 11 <u>CamWest, Inc. and CamWest Limited Partnership</u> Appendix 4-B

Endnotes:

- 1. MIT
- 2. This settlement reflects a "no double-dipping" concept. For penalty calculation purposes, at those wells with mechanical integrity violations that are also in violation of another requirement, only one of the violations is cited for a given date of non-compliance. Further, for wells whose periodic requirement to demonstrate mechanical integrity results in a demonstration of no mechanical integrity, a 90-day grace period is honored. Example: if a well is late demonstrating mechanical integrity as of February 1 (violation = late mechanical integrity demonstration), and then on April 1 a mechanical integrity test is performed in which the well fails (violation = failure to establish and maintain mechanical integrity), it is not until July 1 that a penalty for the failure to establish and maintain mechanical integrity violation commences). In this example, on April 1, both violations commence running simultaneously, since the requirement to periodically demonstrate mechanical integrity still has not abated, and the well has lost mechanical integrity. This method is being applied here simply as one approach to a settlement and has no policy or legal merit otherwise.
- 3. MI = Mechanical integrity
- 4. PA = plug and abandon